



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

AFS #42-003-00032
AIR-ICIS#PAACH00042003
00032
JIM H.

July 13, 2015

RECEIVED

JUL 21 2015

Air Protection Division

Ms. Rita Hirschfield
Allegheny County Health Department
Department of Air Quality
301 Thirty-Ninth Street
Pittsburgh, PA 15201

Subject: USS Reference Number: 15-0178
ACHD Reference Number: 18981
Sulfur Plant
USS Clairton Works

Dear Rita Hirschfield,

The attached form terminates the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Jonelle S. Scheetz at 412-233-1015.

Sincerely,

Michael S. Rhoads
Plant Manager
Clairton Works

CC: James W. Hagedorn (USEPA)

NOTICE OF OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 15-0178 Termination
ACHD Reference Number: 18981
2. Date & Time of Breakdown: Date: 07/08/15 Time: 0700 hours
3. Company Name: U.S. Steel Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: Sulfur Plant
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: The 101J sulfur plant vacuum axi is unavailable for service to repair the lubrication system. The 101J Axi is a redundant piece of equipment. The spare C658 Axi will carry the full load. Sulfur Plant performance will not be affected and emissions will not increase due to this work.
8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
The spare C658 Axi will carry the full load. No environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. Amount of each type emitted (or likely to be emitted).
N/A
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).
The spare C658 Axi carried the full gas flow to the plant.
10. Facility back in operation - Date: 07/10/15 Time: 1500 hours

Reviewed by Jonelle S. Scheetz Date 7/15/15
Jonelle S. Scheetz
Environmental Control Engineer Phone: 412-233-1015